

## Installation of BACNET driver fails – IMP-C Panel PC w/Windows 10

### **Error:**

When installing the BACNET driver you may receive the following error message:

"There is a problem with this Windows Installer package. A program run as part of the setup did not finish as expected. Contact your support personnel or package vendor"

### **Cause:**

This error message may appear if you are trying to install the BACNET driver on a machine that has no network interface available. Please ensure that a network adapter is installed on the machine and a network connection is available.

### **Affected models:**

IMP-CnnnPT models with Windows 10 64Bit OS. Intel 82574L Gb Ethernet adapters with Microsoft drivers version 12.12.50.6 (20/3/2015).


### **Solution:**

Update the drivers for the network adapter, and then retry the installation of the BACNET driver.


Updating the network adapter drivers:

1. Download the following driver from Intel:  
<https://downloadmirror.intel.com/18713/eng/PROWinx64.exe>
2. Extract the driver package to a folder.
3. Go to Device Manager.


- Expand category “Network adapters”. Right-click on the Intel network device and select **Update Driver Software...**




- Click **Browser my computer for driver software.**




6. Click **Let me pick from a list of device drivers on my computer.**



7. Click **Have Disk...** button.




8. Click **Browse...** button and navigate to the folder with the extracted files, e.g. ...\\PRO1000\\Winx64\\NDIS64




Click **Open** and then **OK**.


9. A list of drivers will be shown. Select the driver called **Intel(R) 82579LM...** and click **Next**.



10. Click **Yes** if the following warning appears:



11. The driver is successfully installed.



12. The driver version has been updated to Intel v. 12.15.31.4 (29.03.16)

