APPC Touch Screen - Re-calibrate the touch

1. Right click the eGalax Touch icon in the system tray



2. Select Calibration utility



3. Click on the tab "Tools" in eGalaxTouch window

Edge Compensation Hardware About General Setting Tool
Installed Touchscreen Controllers
(D)
Monitor Mapping Add Plemove

4. Click on the button "Clear and Calibrate"

	Edge Compensation General	n Setting	Hardware Tools	4	About Display	l
6	Linearization Curve			0.07		
						7
	4 Points Calibration	Do 4 point	s alignment to m	atch disp	lay.	b.
	Clear and Cribrate	Clear linearization parameter and do 4 alignment.		4 points		
	Linearization	Do 25 poir linearity.	its linearization f	or better	touchscreen	
	Draw Test	Do draw te	est to verify the t	ouch ac	curacy.	
		0	Car	icel	Apply	

5. Follow the instructions to calibrate the touch. Press each point as accurately as possible.



6. When done, click OK

9	eGalaxTouch : USB G	Controller		2	3
7	Edge Compensatio	on Setting	Hardware Tools	About Display	
	Linearization Curve			1	1
			10		
					×
(xt	kutility				
xt	kutility				ġ 🖌
xt	kutility	141 1.2			
xt	kutility	libration co	mpleted. Press[Ok	to continue.	
xt	kutility	libration co	mpleted. Press[Ok	to continue.	
x	kutility	libration co	mpleted. Press[Ok]	to continue.	
x	kutility	libration co	mpleted. Press[0k	to continue.	
	kutility	libration co	mpleted. Press[Ok	to continue.	
	kutility 4 points ca Linearization Draw Test	libration co	mpleted. Press[Ok	to continue.	

eGalaxTouch: USB Co	ontroller		23	1	
Edge Compensation	1	Hardware	About		
General	Setting	10015	Display		
Linearization Curve					
4 Points Calibration	Do 4 poir	nts alignment to match	n display.	de la	
Clear and Calibrate	Clear line alignment	arization parameter a t.	nd do 4 points		
Linearization	Do 25 points linearization for better touchscreen linearity.				
Draw Test	Do draw	test to verify the touc	h accuracy.		
		K Cancel	Anniu		

7. Click OK to close the eGalaxTouch window

8. Test that the touch is working OK. If not, rerun the calibration.