



## Calibrate the touch screen using PenMount Control Panel

1. Open PenMount Control Panel by clicking Start, type PenMount Control Panel...


or go to Start -> All Programs -> PenMount Windows Universal... -> Utility -> PenMount Control Panel menu.



2. Click "Configure" button at PenMount Control Panel.



3. Click "Standard Calibration" at Device 0 window.



4. Follow the on-screen instructions.

